



Hubshell
100

A NDS Flange \varnothing
57mm

B NDS Center to Flange
22mm

C DS Center to Flange
38mm

D DS Flange \varnothing
39mm

For Flange to Dropout Value Subtract Center to Flange Value from 1/2 of Dropout Spacing