



**Hubshell**  
130

**A** NDS Flange  $\varnothing$   
50mm

**B** NDS Center to Flange  
35mm

**C** DS Center to Flange  
17.5mm

**D** DS Flange  $\varnothing$   
59mm

\*For Flange to Dropout Value Subtract Center to Flange Value from 1/2 of Dropout Spacing\*